MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS BUREAU OF CONSTRUCTION CODES/BOILER DIVISION P.O. BOX 30254, LANSING, MICHIGAN 48909 517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 1965 PA 290, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 1965 PA 290 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

DIRECTOR BCC-300 (Rev. 1/14)	Shelly Edgerton	5363 44th St SE Grand Rapids, MI 49512-4093	West Michigan Aviation Academy	OCATION	5363 44th St SE Grand Rapids, MI 49512-4093	West Michigan Aviation Academy	OWNER/USER
PLACE IN BOILER ROOM		INSPECTOR:	SV PRESS:	MAX OPR PRESS: 125	YEAR BUILT:	BOILER TYPE:	MANUFACTURER: Lochinvar
ER ROOM		Michael P. Smith	125	S : 125	2012	Water Tube	:R: Lochinvar
Chief, Boiler Division	David Stenrose			EXP DATE:	DATE INSP: 10/10/2018	NB# / MFG#:	STATE NO:
ä				10/10/2021	10/10/2018	226129	MIR432052

N600953

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS BUREAU OF CONSTRUCTION CODES/BOILER DIVISION P.O. BOX 30254, LANSING, MICHIGAN 48909 517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 1965 PA 290, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 1965 PA 290 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

BCC-300 (Rev. 1/14)	Shelly Edgerton	5363 44th St SE Grand Rapids, MI 49512-4093	West Michigan Aviation Academy	LOCATION	5363 44th St SE Grand Rapids, MI 49512-4093	West Michigan Aviation Academy	CWNERYCORK
ÓR	yerton		emy			emy	
PLACE IN BOILER ROOM		INSPECTOR:	SV PRESS:	MAX OPR PRESS: 125	YEAR BUILT:	BOILER TYPE:	MANUFACTURER: Lochinvar
ER ROOM		Michael P. Smith	50	iS: 125	2012	Water Tube	R: Lochinvar
Chief, Boiler Division	David Stenrose			EXP DATE: 10/10/202	DATE INSP: 10/10/2018	NB#/MFG#: 214472	STATE NO: MIR431437
on				10/10	10/10.	21447	MIR4

N600952

MICHIGAN DEPARTMENT OF LICENSING AND REGULATORY AFFAIRS
BUREAU OF CONSTRUCTION CODES/BOILER DIVISION
P.O. BOX 30254, LANSING, MICHIGAN 48909
517-241-9334

CERTIFICATE OF BOILER INSPECTION

THE HEREIN DESCRIBED BOILER IS APPROVED FOR OPERATION AT A PRESSURE NOT TO EXCEED THE MAXIMUM OPERATING PRESSURE SPECIFIED HEREON, PROVIDED THE OWNER/USER HAS COMPLIED WITH ALL REQUIREMENTS OF 1965 PA 290, AS AMENDED AND THE RULES AND REGULATIONS PROMULGATED BY THE DIRECTOR OF THE DEPARTMENT. INSTALLATION, REINSTALLATION, ALTERATION, OR REPAIR OF THIS BOILER MUST BE IN STRICT CONFORMITY WITH THE REQUIREMENTS OF 1965 PA 290 AND THE BOILER RULES AND REGULATIONS. THE HOLDER OF THIS CERTIFICATE SHALL NOTIFY THE CHIEF INSPECTOR OF EVERY ACCIDENT INVOLVING PERSONAL INJURY OR DAMAGE TO THIS BOILER.

BCC-300 (Rev. 1/14)	5363 44th St SE Grand Rapids, MI 49512-4093	West Michigan Aviation Academy	OCCUPATION	5363 44th St SE Grand Rapids, MI 49512-4093	West Michigan Aviation Academy	OWNER/USER
PLACE IN BOILER ROOM	INSPECTOR: Michael P. Smith	SV PRESS: 50	MAX OPR PRESS: 125	YEAR BUILT: 2012	BOILER TYPE: Water Tube	MANUFACTURER: Lochinvar
Chief, Boiler Division	David Stenrose		EXP DATE:	DATE INSP:	NB# / MFG#:	STATE NO:
3			10/10/2021	10/10/2018	#: 213426	MIR431436